ZINC GALVANISING SPRAY

Page 1 Issued: 23/08/2005

Revision No: 2

1. IDENTIFICATION OF THE SUBSTANCE / PREPARATION AND OF THE COMPANY / UNDERTAKING

Product name: ZINC GALVANISING SPRAY

Synonyms: ZGS500

Use / description of product: The regulatory information is dependent upon the concentration limit of the specific substance.

Company name: Specialised Aerosols Company Limited

Carr Green Lane Mapplewell Barnsley South Yorkshire S75 6DY Tel: 01226 387100

2. COMPOSITION / INFORMATION ON INGREDIENTS

Hazardous ingredients: XYLENE 1-10%

EINECS: 215-535-7 CAS: 1330-20-7

[-] R10; [Xn] R20/21; [Xi] R38

- ACETONE 10-30%
 EINECS: 200-662-2 CAS: 67-64-1
 [F] R11; [Xi] R36; [Xi] R66; [-] R67
- BUTANE 10-30%
 EINECS: 203-448-7 CAS: 106-97-8
 [F+] R12
- LOW BOILING POINT HYDROGEN TREATED NAPHTHA NAPHTHA (PETROLEUM), HYDRODESULPHURIZED HEAVY <1% EINECS: 265-185-4 CAS: 64742-82-1

[-] R10; [N] R51/53; [Xn] R65

3. HAZARDS IDENTIFICATION

Main hazards: Extremely flammable. Irritating to eyes. Repeated exposure may cause skin dryness or cracking.

Vapours may cause drowsiness and dizziness.

Other hazards: In use, may form flammable / explosive vapour-air mixture.

4. FIRST AID MEASURES (SYMPTOMS)

| Skin contact: | There may be irritation and redness at the site of contact. | |
|---------------|--|---------|
| Eye contact: | : There may be irritation and redness. | |
| Ingestion: | Nausea and stomach pain may occur. There may be vomiting. Inhalation of fumes from the | |
| | stomach may cause symptoms similar to direct inhalation. | |
| Inhalation: | Inhalation: Nausea and stomach pain may occur. There may be vomiting. Drowsiness or mental confusion | |
| | may occur. There may be loss of consciousness. | [cont_] |

SAFETY DATA SHEET

ZINC GALVANISING SPRAY

| Extinguishing media: Carbon dioxide. Exposure hazards: Extremely flammable. In combustion emits toxic fumes. Vapour may travel considerable distance to source of ignition and flash back. Forms explosive air-vapour mixture. Protection of fire-fighters: Wear self-contained breathing apparatus. Wear protective clothing to prevent contact with skin and eyes. 6. ACCIDENTAL RELEASE MEASURES Personal precautions: Eliminate all sources of ignition. Mark out the contaminated area with signs and prevent access to unauthorised personnel. Turn leaking containers leak-side up to prevent the escape of liquid. Environmental precautions: Do not discharge into drains or rivers. Contain the spillage using bunding. Clean-up procedures: Absorb into dry earth or sand. Transfer to a closable, labelled salvage container for disposal by an appropriate method. Wash the spillage site with large amounts of water. Do not use equipment in clean-up procedure which may produce sparks. 7. HANDLING AND STORAGE Handling requirements: Ensure there is sufficient ventilation of the area. Avoid direct contact with the substance. Smoking is forbidden. Use non-sparking tools. Storage conditions: Store in cool, well ventilated area. Keep away from sources of ignition. Keep container tightly closed. | 4. FIRST AID MEASURES | | | |
|---|--|--|--|--|
| hospital if there are burns or symptoms of poisoning. Eye contare: Bathe the eye with running water for 15 minutes. Transfer to hospital for specialist examination. Ingestion: Do not induce vomiting. If conscious, give half a litre of water to drink immediately. If unconscious, and breathing and apply artificial respiration if necessary. If unconscious and breathing is OK, place in the recovery position. Transfer to hospital as soon as possible. Inhalation: Remove casality from exposure ensuring one's own safety whils doing so. If unconscious, eleck for breathing and apply artificial respiration if necessary. If unconscious and breathing is OK, place in the recovery position. If conscious, ensure the casality sits or lies down. If breathing becomes bubbly, have the casality sit and provide oxygen if available. Transfer to hospital as soon as possible. 5. FIRE-FIGHTING MEX-VEET Extinguishing media: Carbon dioxide. Exposure hazards: Extremely flammable. In combustion emits toxic fumes. Vapour may travel considerable distance to source of ignition and flash back. Forms explosive air-vapour mixture. Protection of fire-fighters: Wear self-contained breathing apparatus. Wear protective clothing to prevent contact with skin and eyes. Chean-up procedure: Eliminate all sources of ignition. Mark out the contaminated area with signs and prevent access to unauthorised personnel. Turn leaking containers leak-side up to prevent the escape of liquid. Exvironmental precautions: Do not discharge into drains or rivers. Contain the spillage using bunding. | Skin contact: | Remove all contaminated clothes and footwear immediately unless stuck to skin. Drench the | | |
| Eye contact: Bathe the eye with running water for 15 minutes. Transfer to hospital for specialist examination. Ingestion: Do not induce vomiting. If conscious, give half a litre of water to drink immediately. If unconscious, and breathing is OK, place in the recovery position. Transfer to hospital as soon as possible. Inhalation: Remove casually from exposure ensuring one's own safety whilst doing so. If neconscious, eleck for breathing and apply artificial respiration if necessary. If unconscious and breathing is OK, place in the recovery position. Transfer to hospital as soon as possible. 5. FIRE-FIGHTING MEX-VEES Externely flammable. In combustion emits toxic fumes. Vapour may travel considerable distance to source of ignition and flash back. Forms explosive air-vapour mixture. Protection of fire-fighter: Wear self-contained breathing apparatus. Wear protective clothing to prevent contact with skin and eyes. ACCIDENTAL RELEXENTES Esternely flammable. In combustion emits toxic fumes. Vapour may travel considerable distance to source of ignition and flash back. Forms explosive air-vapour mixture. Protection of fire-fighter: Wear self-contained breathing apparatus. Wear protective clothing to prevent contact with skin and eyes. CLODENTAL RELEXENTES Do not discharge into drains or rivers. Contain the spillage using bunding. Clean-up procedures: Do not discharge into drains or rivers. Contain the spillage using bunding. Clean-up procedures: Estoredure which may produce sparks. 7. HANDLING AND STOVEVE </td <td></td> <td>affected skin with running water for 10 minutes or longer if substance is still on skin. Transfer to</td> | | affected skin with running water for 10 minutes or longer if substance is still on skin. Transfer to | | |
| Ingestion: Do not induce vomiting. If conscious, give half a litre of water to drink immediately. If unconscious, check for breathing and apply artificial respiration if necessary. If unconscious and breathing is OK, place in the recovery position. Transfer to hospital as soon as possible. Inhalation: Remove casually from exposure ensuring one's own safety whilst doing so. If unconscious, check for breathing and apply artificial respiration if necessary. If unconscious, and breathing is OK, place in the recovery position. If conscious, ensure the casualty sits or lies down. If breathing becomes bubbly, have the casualty sit and provide oxygen if available. Transfer to hospital as soon as possible. 5. FIRE-FIGHTING MEXTERS Extremely flammable. In combustion emits toxic fumes. Vapour may travel considerable distance to source of ignition and flash back. Forms explosive air vapour mixture. Protection of fire-fighters: Wear self-contained breathing apparatus. Wear protective clothing to prevent contact with skin and eyes. 6. ACCIDENTAL RELEASE MEASURES Do not discharge into drains or rivers. Contain the spillage using bunding. Clean-up procedures: Absorb into dry earth or sand. Transfer to a closable, labelled salvage container for disposal by an appropriate method. Wash the spillage site with large anounts of water. Do not use equipment in clean-up procedure which may produce sparks. 7. HANDLING AND STOKEVE Handling requirements: Barding requirements: Ensure there is sufficient ventilation of the area. Avoid direct contact with the substance. Storing conditions: <td></td> <td>hospital if there are burns or symptoms of poisoning.</td> | | hospital if there are burns or symptoms of poisoning. | | |
| unconscious, check for breathing and apply artificial respiration if necessary. If unconscious and breathing is OK, place in the recovery position. Transfer to hospital as soon as possible. Inhalation: Remove casualty from exposure ensuring one's own safety whilst doing so. If unconscious, check for breathing and apply artificial respiration if necessary. If unconscious and breathing is OK, place in the recovery position. If conscious, ensure the casualty sits or lies down. If breathing becomes bubbly, have the casualty sit and provide oxygen if available. Transfer to hospital as soon as possible. 5. FIRE-FIGHTING MEAS-UEES Extinguishing media: Carbon dioxide. Exposure hazards: Extremely flammable. In combustion emits toxic fumes. Vapour may travel considerable distance to source of ignition and flash back. Forms explosive air-vapour mixture. Protection of fire-fighters: Wear self-contained breathing apparatus. Wear protective clothing to prevent contact with skin and eyes. 6. ACCIDENTAL RELEAS-UEASURES Personal precautions: Eliminate all sources of ignition. Mark out the contaminated area with signs and prevent access to unauthorised personnel. Turn leaking containers leak-side up to prevent the escape of liquid. Environmental precautions: Absorb into dry earth or sand. Transfer to a closable, labelled salvage container for disposal by an appropriate method. Wash the spillage site with large amounts of water. Do not use equipment in clean-up procedure which may produce sparks. 7. HANDLING AND STOKEF Handling requirements: Store in cool, well ventilated area. Keep away from sources of ignition. Keep container tightly closed. 8. EXPOSURE CONTROKES/ PERSONAL PROTECTION Kazdous ingrediems: XYLENE TWA 220 mg/m3 STEL 441 mg/m3 | Eye contact: | Bathe the eye with running water for 15 minutes. Transfer to hospital for specialist examination. | | |
| and breathing is OK, place in the recovery position. Transfer to hospital as soon as possible. Inhalation: Remove casualty from exposure ensuring one's own safety whilst doing so. If unconscious, check for breathing and apply artificial respiration if necessary. If unconscious and breathing is OK, place in the recovery position. If conscious, ensure the casualty sits or lies down. If breathing becomes bubbly, have the casualty sit and provide oxygen if available. Transfer to hospital as soon as possible. 5. FIRE-FIGHTING MEASURES Extinguishing media: Carbon dioxide. Exposure hazares: Extremely flammable. In combustion emits toxic fumes. Vapour may travel considerable distance to source of ignition and flash back. Forms explosive air-vapour mixture. Protection of fire-fighter: Wear self-contained breathing apparatus. Wear protective clothing to prevent contact with skin and eyes. 6. ACCIDENTAL RELEASE MEASURES Personal precautions: Eliminate all sources of ignition. Mark out the contaminated area with signs and prevent access to unauthorised personnel. Turn leaking containers leak-side up to prevent the escape of liquid. Environmental precautions: Above into dry earth or sand. Transfer to a closable, labelled salvage container for disposal by an appropriate method. Wash the spillage site with large amounts of water. Do not use equipment in clean-up procedure which may produce sparks. 7. HANDLING AND STOKEE Mandling requirements: Store in cool, well ventilation of the area. Avoid direct contact with the substance. Smoking is forbidden. Use non-sparking tools. 8. Storage conditions: PERSONAL PROTECTION Hazardous ingrediem: XYLENE Twa 220 mg/m3 STEL 441 mg/m3 | Ingestion: | Do not induce vomiting. If conscious, give half a litre of water to drink immediately. If | | |
| Inhalation: Remove casually from exposure ensuring one's own safety whilst doing so. If unconscious, check for breathing and apply artificial respiration if necessary. If unconscious and breathing is OK, place in the recovery position. If conscious, ensure the casualty sits or lies down. If breathing becomes bubbly, have the casualty sit and provide oxygen if available. Transfer to hospital as soon as possible. 5. FIRE-FIGHTING MEX | | unconscious, check for breathing and apply artificial respiration if necessary. If unconscious | | |
| check for breathing and apply artificial respiration if necessary. If unconscious and breathing is OK, place in the recovery position. If conscious, ensure the casualty sits or lies down. If breathing becomes bubbly, have the casualty sit and provide oxygen if available. Transfer to hospital as soon as possible. 5. FIRE-FIGHTING MEASURES Extinguishing media Carbon dioxide. Exposure hazards Extremely flammable. In combustion emits toxic fumes. Vapour may travel considerable distance to source of ignition and flash back. Forms explosive air-vapour mixture. Protection of fire-fighters: Wear self-contained breathing apparatus. Wear protective clothing to prevent contact with skin and eyes. 6. ACCIDENTAL RELEXE MEASURES Personal precautions: Eliminate all sources of ignition. Mark out the contaminated area with signs and prevent access to unauthorised personnel. Turn leaking containers leak-side up to prevent the escape of liquid. Environmental precautions: Do not discharge into drains or rivers. Contain the spillage using bunding. Clean-up procedures: Absorb into dry earth or sand. Transfer to a closable, labelled salvage container for disposal by an appropriate method. Wash the spillage site with large amounts of water. Do not use equipment in clean-up procedure which may produce sparks. 7. HANDLING AND STUCKEE Handling requirements: Ensure there is sufficient ventilation of the area. Avoid direct contact with the substance. Smoking is forbidden. Use non-sparking tools. Storage conditions: Store in cool, well ventilated area. Keep away from sources of ignition. Keep container tightly closed. EXENOSURE CONTRUC | | and breathing is OK, place in the recovery position. Transfer to hospital as soon as possible. | | |
| OK, place in the recovery position. If conscious, ensure the casualty sits or lies down. If breathing becomes bubbly, have the casualty sit and provide oxygen if available. Transfer to hospital as soon as possible. 5. FIRE-FIGHTING MEASURES Extinguishing media: Carbon dioxide. Exposure hazards: Extremely flammable. In combustion emits toxic fumes. Vapour may travel considerable distance to source of ignition and flash back. Forms explosive air-vapour mixture. Protection of fire-fighters: Wear self-contained breathing apparatus. Wear protective clothing to prevent contact with skin and eyes. 6. ACCIDENTAL RELEASURES Eliminate all sources of ignition. Mark out the contaminated area with signs and prevent access to unauthorised personnel. Turn leaking containers leak-side up to prevent the escape of liquid. Environmental precautions: Eliminate all sources of ignition. Mark out the contaminated area with signs and prevent access to unauthorised personnel. Turn leaking containers leak-side up to prevent the escape of liquid. Clean-up procedures: Absorb into dry earth or sand. Transfer to a closable, labelled salvage container for disposal by an appropriate method. Wash the spillage site with large amounts of water. Do not use equipment in clean-up procedure which may produce sparks. 7. HANDLING AND STO- Ensure there is sufficient ventilation of the area. Avoid direct contact with the substance. Smoking is forbidden. Use non-sparking tools. Storage conditions: Store in cool, well ventilated area. Keep away from sources of ignition. Keep container tightly closed. | Inhalation: | Remove casualty from exposure ensuring one's own safety whilst doing so. If unconscious, | | |
| breathing becomes bubbly, have the casualty sit and provide oxygen if available. Transfer to hospital as soon as possible. 5. FIRE-FIGHTING MEX-URES Extinguishing media: Carbon dioxide. Exposure hazards: Extremely flammable. In combustion emits toxic fumes. Vapour may travel considerable distance to source of ignition and flash back. Forms explosive air-vapour mixture. Protection of fire-fighters: Wear self-contained breathing apparatus. Wear protective clothing to prevent contact with skin and eyes. 6. ACCIDENTAL RELEX-URES Eliminate all sources of ignition. Mark out the contaminated area with signs and prevent access to unauthorised personnel. Turn leaking containers leak-side up to prevent the escape of liquid. Environmental precautions: Eliminate all sources of ignition. Mark out the contaminated area with signs and prevent access to unauthorised personnel. Turn leaking containers leak-side up to prevent the escape of liquid. Environmental precautions: Do not discharge into drains or rivers. Contain the spillage using bunding. Clean-up procedures: Absorb into dry earth or sand. Transfer to a closable, labelled salvage container for disposal by an appropriate method. Wash the spillage site with large amounts of water. Do not use equipment in clean-up procedure which may produce sparks. 7. HANDLING AND STO | | check for breathing and apply artificial respiration if necessary. If unconscious and breathing is | | |
| Inspital as soon as possible. 5. FIRE-FIGHTING ME-SUBSE Extinguishing media: Carbon dixide. Exposure hazards: Extremely flammable. In combustion emits toxic fumes. Vapour may travel considerable distance to source of ignition and flash back. Forms explosive air-vapour mixture. Protection of fire-fighters: Wear self-contained breathing apparatus. Wear protective clothing to prevent contact with skin and eyes. 6. ACCIDENTAL RELE-SUBSE MEASURES Personal precautions: Eliminate all sources of ignition. Mark out the contaminated area with signs and prevent access to unauthorised personnel. Turn leaking containers leak-side up to prevent the escape of liquid. Environmental precautions: Do not discharge into drains or rivers. Contain the spillage using bunding. Clean-up procedures: Absorb into dry earth or sand. Transfer to a closable, labelled salvage container for disposal by an appropriate method. Wash the spillage site with large amounts of water. Do not use equipment in clean-up procedure which may produce sparks. 7. HANDLING AND STO-EVE Storage conditions: Rote in cool, well ventilated area. Keep away from sources of ignition. Keep container tightly closed. Storage conditions: Store in cool, well ventilated area. Keep away from sources of ignition. Keep container tightly closed. Storage conditions: Store in cool, well ventilated area. Keep away from sources of ignition. Keep container tightly closed. S | | OK, place in the recovery position. If conscious, ensure the casualty sits or lies down. If | | |
| 5. FIRE-FIGHTING MEASURES Extinguishing media: Carbon dioxide. Exposure hazards: Extremely flammable. In combustion emits toxic fumes. Vapour may travel considerable distance to source of ignition and flash back. Forms explosive air-vapour mixture. Protection of fire-fighters: Wear self-contained breathing apparatus. Wear protective clothing to prevent contact with skin and eyes. 6. ACCIDENTAL RELEASE MEASURES Eliminate all sources of ignition. Mark out the contaminated area with signs and prevent access to unauthorised personnel. Turn leaking containers leak-side up to prevent the escape of liquid. Environmental precautions: Do not discharge into drains or rivers. Contain the spillage using bunding. Clean-up procedures: Absorb into dry earth or sand. Transfer to a closable, labelled salvage container for disposal by an appropriate method. Wash the spillage site with large amounts of water. Do not use equipment in clean-up procedure which may produce sparks. 7. HANDLING AND STOR-GE Handling requirements: Ensure there is sufficient ventilation of the area. Avoid direct contact with the substance. Smoking is forbidden. Use non-sparking tools. Storage conditions: Store in cool, well ventilated area. Keep away from sources of ignition. Keep container tightly closed. 8. EXPOSURE CONTROL / PERSONAL PROTECTION KYLENE Hazardous ingredients: XYLENE TWA 220 mg/m3 STEL 441 mg/m3 <th></th> <th>breathing becomes bubbly, have the casualty sit and provide oxygen if available. Transfer to</th> | | breathing becomes bubbly, have the casualty sit and provide oxygen if available. Transfer to | | |
| Extinguishing media: Carbon dioxide. Exposure hazards: Extremely flammable. In combustion emits toxic fumes. Vapour may travel considerable distance to source of ignition and flash back. Forms explosive air-vapour mixture. Protection of fire-fighters: Wear self-contained breathing apparatus. Wear protective clothing to prevent contact with skin and eyes. 6. ACCIDENTAL RELEASE MEASURES Personal precautions: Eliminate all sources of ignition. Mark out the contaminated area with signs and prevent access to unauthorised personnel. Turn leaking containers leak-side up to prevent the escape of liquid. Environmental precautions: Do not discharge into drains or rivers. Contain the spillage using bunding. Clean-up procedures: Absorb into dry earth or sand. Transfer to a closable, labelled salvage container for disposal by an appropriate method. Wash the spillage site with large amounts of water. Do not use equipment in clean-up procedure which may produce sparks. 7. HANDLING AND STOR-KEE Ensure there is sufficient ventilation of the area. Avoid direct contact with the substance. Smoking is forbidden. Use non-sparking tools. Storage conditions: Store in cool, well ventilated area. Keep away from sources of ignition. Keep container tightly closed. 8. EXPOSURE CONTROL: / PERSONAL PROTECTION Hazardous ingredient: XYLENE TWA 220 mg/m3 STEL 441 mg/m3 | | hospital as soon as possible. | | |
| Exposure hazards:Extremely flammable. In combustion emits toxic fumes. Vapour may travel considerable distance to source of ignition and flash back. Forms explosive air-vapour mixture.Protection of fire-fighters:Wear self-contained breathing apparatus. Wear protective clothing to prevent contact with skin and eyes.6. ACCIDENTAL RELEASE MEASURESPersonal precautions:Eliminate all sources of ignition. Mark out the contaminated area with signs and prevent access to unauthorised personnel. Turn leaking containers leak-side up to prevent the escape of liquid.Environmental precautions:Do not discharge into drains or rivers. Contain the spillage using bunding.Clean-up procedures:Absorb into dry earth or sand. Transfer to a closable, labelled salvage container for disposal by an appropriate method. Wash the spillage site with large amounts of water. Do not use equipment in clean-up procedure which may produce sparks.7. HANDLING AND STOR-KGEHandling requirements:Ensure there is sufficient ventilation of the area. Avoid direct contact with the substance. Smoking is forbidden. Use non-sparking tools.Storage conditions:Store in cool, well ventilated area. Keep away from sources of ignition. Keep container tightly closed.B. EXPOSURE CONTROL:PERSONAL PROTECTIONHazardous ingredients:XYLENE TWA 220 mg/m3_STEL 441 mg/m3 | 5. FIRE-FIGHTING MEA | SURES | | |
| b o source of ignition and flash back. Forms explosive air-vapour mixture. Wear self-contained breathing apparatus. Wear protective clothing to prevent contact with skin and eyes. 6. ACCIDENTAL RELEASURES Personal precautions: Eliminate all sources of ignition. Mark out the contaminated area with signs and prevent access to unauthorised personnel. Turn leaking containers leak-side up to prevent the escape of liquid. Environmental precautions: Clean-up procedures: Absorb into dry earth or sand. Transfer to a closable, labelled salvage container for disposal by an appropriate method. Wash the spillage site with large amounts of water. Do not use equipment in clean-up procedure which may produce sparks. 7. HANDLING AND STOENET Handling requirements: Storage conditions: Storage conditions: Storage conditions: 8. EXPOSURE CONTROENET Hazardous ingrediemt: XYLENE TWA 220 mg/m3 STEL 441 mg/m3 | Extinguishing media: | Carbon dioxide. | | |
| Protection of fire-fighters: Wear self-contained breathing apparatus. Wear protective clothing to prevent contact with skin and eyes. 6. ACCIDENTAL RELEASE MEASURES Personal precautions: Eliminate all sources of ignition. Mark out the contaminated area with signs and prevent access to unauthorised personnel. Turn leaking containers leak-side up to prevent the escape of liquid. Environmental precautions: Do not discharge into drains or rivers. Contain the spillage using bunding. Clean-up procedures: Absorb into dry earth or sand. Transfer to a closable, labelled salvage container for disposal by an appropriate method. Wash the spillage site with large amounts of water. Do not use equipment in clean-up procedure which may produce sparks. 7. HANDLING AND STORAGE Handling requirements: Ensure there is sufficient ventilation of the area. Avoid direct contact with the substance. Smoking is forbidden. Use non-sparking tools. Storage conditions: Store in cool, well ventilated area. Keep away from sources of ignition. Keep container tightly closed. 8. EXPOSURE CONTROLS / PERSONAL PROTECTION Hazardous ingredients: XYLENE TWA 220 mg/m3 STEL 441 mg/m3 | Exposure hazards: | Extremely flammable. In combustion emits toxic fumes. Vapour may travel considerable distance | | |
| ACCIDENTAL RELE>WEASURES ACCIDENTAL RELE>WEASURES Personal precautions: Eliminate all sources of ignition. Mark out the contaminated area with signs and prevent access to unauthorised personnel. Turn leaking containers leak-side up to prevent the escape of liquid. Do not discharge into drains or rivers. Contain the spillage using bunding. Clean-up procedures: Absorb into dry earth or sand. Transfer to a closable, labelled salvage container for disposal by an appropriate method. Wash the spillage site with large amounts of water. Do not use equipment in clean-up procedure which may produce sparks. 7. HANDLING AND STO==================================== | | to source of ignition and flash back. Forms explosive air-vapour mixture. | | |
| 6. ACCIDENTAL RELEASE MEASURES Personal precautions: Eliminate all sources of ignition. Mark out the contaminated area with signs and prevent access to unauthorised personnel. Turn leaking containers leak-side up to prevent the escape of liquid. Environmental precautions: Do not discharge into drains or rivers. Contain the spillage using bunding. Clean-up procedures: Absorb into dry earth or sand. Transfer to a closable, labelled salvage container for disposal by an appropriate method. Wash the spillage site with large amounts of water. Do not use equipment in clean-up procedure which may produce sparks. 7. HANDLING AND STORAGE Handling requirements: Ensure there is sufficient ventilation of the area. Avoid direct contact with the substance. Smoking is forbidden. Use non-sparking tools. Storage conditions: Store in cool, well ventilated area. Keep away from sources of ignition. Keep container tightly closed. 8. EXPOSURE CONTROLS / PERSONAL PROTECTION Hazardous ingredients: XYLENE TWA 220 mg/m3 STEL 441 mg/m3 | Protection of fire-fighters: | Wear self-contained breathing apparatus. Wear protective clothing to prevent contact with skin | | |
| Personal precautions: Eliminate all sources of ignition. Mark out the contaminated area with signs and prevent access to unauthorised personnel. Turn leaking containers leak-side up to prevent the escape of liquid. Environmental precautions: Do not discharge into drains or rivers. Contain the spillage using bunding. Clean-up procedures: Absorb into dry earth or sand. Transfer to a closable, labelled salvage container for disposal by an appropriate method. Wash the spillage site with large amounts of water. Do not use equipment in clean-up procedure which may produce sparks. 7. HANDLING AND STORAGE Handling requirements: Ensure there is sufficient ventilation of the area. Avoid direct contact with the substance. Smoking is forbidden. Use non-sparking tools. Storage conditions: Store in cool, well ventilated area. Keep away from sources of ignition. Keep container tightly closed. 8. EXPOSURE CONTROLS / PERSONAL PROTECTION Hazardous ingredients: XYLENE TWA 220 mg/m3 STEL 441 mg/m3 | | and eyes. | | |
| to unauthorised personnel. Turn leaking containers leak-side up to prevent the escape of liquid.Environmental precautions:Do not discharge into drains or rivers. Contain the spillage using bunding.Clean-up procedures:Absorb into dry earth or sand. Transfer to a closable, labelled salvage container for disposal by an appropriate method. Wash the spillage site with large amounts of water. Do not use equipment in clean-up procedure which may produce sparks.7. HANDLING AND STOR-EHandling requirements:Ensure there is sufficient ventilation of the area. Avoid direct contact with the substance. Smoking is forbidden. Use non-sparking tools.Storage conditions:Store in cool, well ventilated area. Keep away from sources of ignition. Keep container tightly closed.8. EXPOSURE CONTROL-> PERSONAL PROTECTIONHazardous ingredients:XYLENE TWA 220 mg/m3TWA 220 mg/m3STEL 441 mg/m3 | 6. ACCIDENTAL RELEA | SE MEASURES | | |
| Environmental precautions: Do not discharge into drains or rivers. Contain the spillage using bunding. Clean-up procedures: Absorb into dry earth or sand. Transfer to a closable, labelled salvage container for disposal by an appropriate method. Wash the spillage site with large amounts of water. Do not use equipment in clean-up procedure which may produce sparks. 7. HANDLING AND STORAGE Handling requirements: Ensure there is sufficient ventilation of the area. Avoid direct contact with the substance. Smoking is forbidden. Use non-sparking tools. Storage conditions: Store in cool, well ventilated area. Keep away from sources of ignition. Keep container tightly closed. 8. EXPOSURE CONTROLS / PERSONAL PROTECTION Hazardous ingredients: XYLENE TWA 220 mg/m3 STEL 441 mg/m3 | Personal precautions: | Eliminate all sources of ignition. Mark out the contaminated area with signs and prevent access | | |
| Clean-up procedures: Absorb into dry earth or sand. Transfer to a closable, labelled salvage container for disposal by an appropriate method. Wash the spillage site with large amounts of water. Do not use equipment in clean-up procedure which may produce sparks. 7. HANDLING AND STORAGE Handling requirements: Ensure there is sufficient ventilation of the area. Avoid direct contact with the substance. Smoking is forbidden. Use non-sparking tools. Storage conditions: Store in cool, well ventilated area. Keep away from sources of ignition. Keep container tightly closed. 8. EXPOSURE CONTROLS / PERSONAL PROTECTION Hazardous ingredients: XYLENE TWA 220 mg/m3 STEL 441 mg/m3 | | to unauthorised personnel. Turn leaking containers leak-side up to prevent the escape of liquid. | | |
| an appropriate method. Wash the spillage site with large amounts of water. Do not use equipment in clean-up procedure which may produce sparks. 7. HANDLING AND STORAGE Handling requirements: Ensure there is sufficient ventilation of the area. Avoid direct contact with the substance. Smoking is forbidden. Use non-sparking tools. Storage conditions: Store in cool, well ventilated area. Keep away from sources of ignition. Keep container tightly closed. 8. EXPOSURE CONTROLS / PERSONAL PROTECTION Hazardous ingredients: XYLENE TWA 220 mg/m3 STEL 441 mg/m3 | Environmental precautions: | Do not discharge into drains or rivers. Contain the spillage using bunding. | | |
| equipment in clean-up procedure which may produce sparks. 7. HANDLING AND STORAGE Handling requirements: Ensure there is sufficient ventilation of the area. Avoid direct contact with the substance. Smoking is forbidden. Use non-sparking tools. Storage conditions: Store in cool, well ventilated area. Keep away from sources of ignition. Keep container tightly closed. 8. EXPOSURE CONTROLS / PERSONAL PROTECTION Hazardous ingredients: XYLENE TWA 220 mg/m3 STEL 441 mg/m3 | Clean-up procedures: | Absorb into dry earth or sand. Transfer to a closable, labelled salvage container for disposal by | | |
| 7. HANDLING AND STORAGE Handling requirements: Ensure there is sufficient ventilation of the area. Avoid direct contact with the substance. Smoking is forbidden. Use non-sparking tools. Storage conditions: Store in cool, well ventilated area. Keep away from sources of ignition. Keep container tightly closed. 8. EXPOSURE CONTROLS / PERSONAL PROTECTION Hazardous ingredients: XYLENE TWA 220 mg/m3 STEL 441 mg/m3 | | an appropriate method. Wash the spillage site with large amounts of water. Do not use | | |
| Handling requirements: Ensure there is sufficient ventilation of the area. Avoid direct contact with the substance. Smoking is forbidden. Use non-sparking tools. Storage conditions: Storage conditions: Store in cool, well ventilated area. Keep away from sources of ignition. Keep container tightly closed. 8. EXPOSURE CONTROLS / PERSONAL PROTECTION Hazardous ingredients: XYLENE TWA 220 mg/m3 STEL 441 mg/m3 | | equipment in clean-up procedure which may produce sparks. | | |
| Smoking is forbidden. Use non-sparking tools. Storage conditions: Store in cool, well ventilated area. Keep away from sources of ignition. Keep container tightly closed. 8. EXPOSURE CONTROLS / PERSONAL PROTECTION Hazardous ingredients: XYLENE TWA 220 mg/m3 STEL 441 mg/m3 | 7. HANDLING AND STOL | RAGE | | |
| Storage conditions: Store in cool, well ventilated area. Keep away from sources of ignition. Keep container tightly closed. 8. EXPOSURE CONTROLS / PERSONAL PROTECTION Hazardous ingredients: XYLENE TWA 220 mg/m3 STEL 441 mg/m3 | Handling requirements: | Ensure there is sufficient ventilation of the area. Avoid direct contact with the substance. | | |
| closed. 8. EXPOSURE CONTROLS / PERSONAL PROTECTION Hazardous ingredients: XYLENE TWA 220 mg/m3 STEL 441 mg/m3 | | | | |
| closed. 8. EXPOSURE CONTROLS / PERSONAL PROTECTION Hazardous ingredients: XYLENE TWA 220 mg/m3 STEL 441 mg/m3 | 0 1 | Smoking is forbidden. Use non-sparking tools. | | |
| Hazardous ingredients: XYLENE TWA 220 mg/m3 STEL 441 mg/m3 | | | | |
| TWA 220 mg/m3 STEL 441 mg/m3 | | Store in cool, well ventilated area. Keep away from sources of ignition. Keep container tightly | | |
| TWA 220 mg/m3 STEL 441 mg/m3 | Storage conditions: | Store in cool, well ventilated area. Keep away from sources of ignition. Keep container tightly closed. | | |
| | Storage conditions: 8. EXPOSURE CONTROL | Store in cool, well ventilated area. Keep away from sources of ignition. Keep container tightly closed. | | |
| | Storage conditions: 8. EXPOSURE CONTROL | Store in cool, well ventilated area. Keep away from sources of ignition. Keep container tightly closed. LS / PERSONAL PROTECTION XYLENE | | |

TWA 1810 mg/m3 STEL 3620 mg/m3

ZINC GALVANISING SPRAY

| • BUTANE | | |
|-------------------------|--|--|
| | TWA 1450 mg/m3 STEL 1810 mg/m3 | |
| Engineering measures: | s: Ensure there is sufficient ventilation of the area. | |
| Respiratory protection: | Self-contained breathing apparatus must be available in case of emergency. | |
| Hand protection: | Protective gloves. | |
| Eye protection: | Safety goggles. | |
| Skin protection: | Protective clothing with elasticated cuffs and closed neck. Boots made of PVC. | |

9. PHYSICAL AND CHEMICAL PROPERTIES

| State: | Aerosol |
|------------------------|---|
| Colour: | Silver |
| Odour: | Solvent. |
| Oxidising: | Non-oxidising (by EC criteria) |
| Solubility in water: | Insoluble |
| Also soluble in: | Re-dispersible in aromatic solvents or ketones. |
| Boiling point/range°C: | >60 |
| Flash point°C: | -10 |
| Relative density: | 0.86kg/m3 |

10. STABILITY AND REACTIVITY

| Stability: | The container is inherently stable under instructed conditions for a reasonable period of time (at |
|------------------------|--|
| | least 24-36 months). |
| Conditions to avoid: | Avoid extremes of temperature. Direct sunlight. Extreme freezing. Avoid exposure to moisture, |
| | which may cause container deterioration and pH, where acidity may damage container integrity. |
| | Avoid sudden impacts, which may damage container integrity. |
| Materials to avoid: | Water. Acids. |
| Haz. decomp. products: | Container corrosion may occur with time and damaged containers should be disposed of before |
| | any danger is evident. Flammable, liquid contents should be considered generally not reactive. |

11. TOXICOLOGICAL INFORMATION

| Hazardous ingredients: | XYLENE |
|------------------------|--|
| | ORL MUS LD50 2119 mg/kg |
| | ORL RAT LD50 4300 mg/kg |
| | SCU RAT LD50 1700 mg/kg |
| • | ACETONE |
| | IVN RAT LD50 5500 mg/kg |
| | ORL MUS LD50 3 gm/kg |
| | ORL RAT LD50 5800 mg/kg |
| Routes of exposure: | THIS IS DESIGNED FOR EXTERNAL USE ONLY. Essentially, when used in this aerosol form, |

ZINC GALVANISING SPRAY

Page 4

there are no potential toxic effects. Deliberate inhalation may cause severe pulmonary and breathing difficulty, dizziness (narcosis) and headaches (but this is unlikely in normal use), and would constitute abuse. Skin and eye irritation may result from continued exposure to vapours when used in areas of poor ventilation, or when working in close proximity to the spray for prolonged periods, and suitable steps should be taken to avoid such conditions. Constituent products have shown no conclusive carcinogenic or mutagenic effects in long term test.

12. ECOLOGICAL INFORMATION

| Mobility: | Will be slow. | |
|-----------------------------------|--|--|
| Persistence and degradability: | Relatively slow though ultimately almost complete. | |
| Bioaccumulative potential: | Accumulation is unlikely once physical breakdown commences. | |
| Other adverse effects: | : Short and long tern effects should not be considered significant. Very short term damage to | |
| | aquatic and soil organisms may occur in large spillages (1000+ containers) though this should | |
| | disperse quickly (especially if absorbent material is used). No effects on plants or animals are | |
| | indicated. No effects on plant or animals are indicated. There is no ozone depletion, ozone | |
| | creation or global warming potential. Water treatment plants would not be affected by small to | |
| | medium volumes of this material. | |
| | | |

13. DISPOSAL CONSIDERATIONS

Disposal of packaging: Do not puncture or incinerate/burn, even after use.

NB: The user's attention is drawn to the possible existence of regional or national regulations regarding disposal.

14. TRANSPORT INFORMATION



ZINC GALVANISING SPRAY

Page 5

| IATA / ICAO | | | |
|--|---|---|--|
| UN no: | 1950 | Class: 2 | |
| Labelling: | 2.1 | | |
| 15. REGULATORY INFO | RMATION | | |
| Hazard symbols: | ols: Highly flammable. | | |
| | Irritant. | | |
| | * | | |
| Risk phrases: | R12: Extremely flammable. | | |
| | R36: Irritating to eyes. | | |
| | R66: Repeated exposure may cause skin | dryness or cracking. | |
| | R67: Vapours may cause drowsiness and | dizziness. | |
| Safety phrases: S2: Keep out of the reach of children. | | | |
| | S16: Keep away from sources of ignition | - No smoking. | |
| S23: Do not breathe vapour. | | | |
| | S37: Wear suitable gloves. | | |
| | S38: In case of insufficient ventilation, w | ufficient ventilation, wear suitable respiratory equipment. | |
| S51: Use only in well-ventilated areas. | | | |
| Precautionary phrases: | Precautionary phrases: Pressurized container: protect from sunlight and do not expose to temperatures exceeding | | |
| | 50°C. Do not pierce or burn, even after u | se. | |
| | Do not spray on a naked flame or any ind | candescent material. Keep away from sources of | |
| | ignition - No smoking. Keep out of the re- | each of children. | |
| Note: | The regulatory information given above of | only indicates the principal regulations specifically | |
| | applicable to the product described in the | safety data sheet. The user's attention is drawn to | |
| | the possible existence of additional provi | sions which complete these regulations. Refer to all | |
| | applicable national, international and loc | al regulations or provisions. | |
| 16. OTHER INFORMATIO |)N | | |
| Risk phrases used in s.2: | R10: Flammable. | | |
| | R20/21: Harmful by inhalation and in con | ntact with skin. | |
| | R38: Irritating to skin. | | |
| | R11: Highly flammable. | | |
| | R36: Irritating to eyes. | | |
| | R66: Repeated exposure may cause skin | dryness or cracking. | |
| | R67: Vapours may cause drowsiness and | dizziness. | |
| | R12: Extremely flammable. | | |
| | | | |

ZINC GALVANISING SPRAY

Page 6

R51/53: Toxic to aquatic organisms, may cause long-term adverse effects in the aquatic environment.

R65: Harmful: may cause lung damage if swallowed.

Legal disclaimer: The above information is believed to be correct but does not purport to be all inclusive and shall be used only as a guide. This company shall not be held liable for any damage resulting from handling or from contact with the above product.